

GENERAL AND REVENUE SECRETARIAT.

190⁶.
(*run*)

File No. *42 of 06*

Serial Nos.

Papers Filed.

Month_____

SUBJECT.

*to Paris to the Venugopala swamy temple
at Chik Malur Chennapattana TK.*

PREVIOUS REFERENCES.

LATER REFERENCES.

557 of 09

Muz 8]

190 3

MUZRAI SECRETARIAT

OFFICE NOTE.

File No. 44-2/

SUBJECT.

Repairs to the Sri Venugopalaswamy temple at Chikka
Mallur, Chennapatna Taluk.

From

The Chief Engineer of Mysore

Memo No 6539

Dated 4th October 1905.

The Chief Engineer has, under instruc-
tions from this Office, submitted estimates
amounting to Rs. 1806 for ^{repairs} ~~preparing~~ the above
mentioned institution.

I inspected this temple on the
24th instant in company with the Assistant En-
gineer Mr. Anandulwar and the Amildar Mr. T.
Ramachandra Rao. The temple is a small but an-
cient one situated on the bank of the Karva
river and is associated with the name of Sage ^{the}

File No. 42 of 906

Muzrai Secretariat.

Kanva Rishi. The main building is in a fairly sound condition, but it is very dark and leaks much. The front Gopuram is quite dilapidated and is in a dangerous condition. The existing compound walls on the Northern and Southern sides also require to be pulled down and re-built, but this work may be deferred for the present as suggested by the Executive Engineer.

It is reported that there will be some difficulty in cutting through the walls for opening out windows. So, the Assistant Engineer and myself are of the opinion that two skylights may be opened on the roof with iron bars all round as has been done in many temples in recent years. This will cost Rs. 300 instead of Rs. 372 provided in the estimate on account of windows.

Thus, the works which are very necessary and which may be sanctioned are the following:-

Rs.222 Removal of Gopuram and repair of Mahadwara and entrance.

Muzrai Secretariat.

File No. 42 of 1906

Rs. 118 Repair of temple roof so as to prevent leakage and other petty repairs.

Rs. 300 Opening out 2 skylights in the Nava ranga on either side.

Rs. 32 Contingencies at 5%

Total Rs. 672/-

The above sum of Rs. 672 may, it is submitted, be sanctioned from the State Grant of the current Official year as the temple has a very small Tasdik and there are no savings.

As the whole cost will be incurred from State funds the Public Works Department may be asked not to charge $10\frac{1}{2}\%$ for Establishment and Tools and plant. This concession has been allowed recently in a few cases under the orders of the Dewan and Councillor.

Submitted to the Dewan thro' the
2nd Councillor.

Quaintance Rao
31/10/06

94
31-10-05

4

Page ()

File No. 142 of 1906

Muzrai Secretariat.

Suzo's proposals
may be approved
4/11/05

yes -
und
9.21.05

9491
7.11.05

Read 11 (night) from lamp
draft acc'd
11/11/05

OK (h...
12/11/05

Muz. S.]

190 .

MUTZRAJ SECRETARIAT.

OFFICE NOTE.

File No

Subject.

Repairs to the Sri Venkateswara Swami temple
at Mallur in the Channarayana Taluk.

From

The Deputy Commissioner, Bangalore District.

Letter No 143 Dated 12th April 1907.

The temple of the Sri Venkateswara Swami at Mallur is situated on the side of the Bangalore & Mysore road and is considered to be an ancient and important one. The Deputy Commissioner submits for sanction an estimate for Rs 580/- for repairing the temple and ~~proposes~~ proposes that the cost may be met from the State Grant.

Sum for order

Rs
23/4/07

We sanctioned about 700 Rs
about

File No. 47 of 1907

Muzrai Secretariat.

about a year ago for repairing this temple and I believe the work has been completed. I do not understand this 2nd reference.

YH 23/4/07

Submitted..

Am A 2/2/11

An Estimate for Rs 672/- for certain repairs to the Sri Venkateswara Swami temple at Chikamallu, Channarayana Taluk, was sanctioned in Govt Pro. no. 2361-3 D) 18th November 1905; the charge being met from the State Grant as no funds were available at the credit of the temple.

The present Estimate provides for the construction of a compound wall and the kitchen attached to the temple.

The Completion bill for the works already sanctioned has not yet been received from the Deputy Commissioner.

25/4/07

ds

Muzrai Secretariat

File No. . . . of 190 6

note continued. —

no 5089 of 29. 4. 07.

The Deputy Commissioner was requested to report as to whether the repair of the Compound wall was of an urgent nature and whether it might not be put off as was decided on ^a former occasion. He was further requested that the Assistant Engineer of the Channarayana Division might be consulted that the Estimate might be checked and revised by him and that if the construction of a kitchen was really necessary, a small Estimate therefor might be separately submitted.

The Chief Engineer was informed accordingly.

no 124 of 1. 5. 08

In reply to the above, the Dy. Commr submits for sanction an Estimate for Rs 1930/- prepared by the P. W. Dopan & Co. providing therein for the following work. —

1. Construction of a kitchen " — — — 240/-

File No. 42 of 1906

Muzrai Secretariat

2. Reconstruction of the Compound wall Rs. 880/-
3. Repairs to main temple ——— Rs. 120/-
4. Repairs to Sri Anjaneya Swami temple Rs. 274/-
5. Est. tools and plant charges ——— 266/-

He further states that the Sub Dn Officer of closest reports that the construction of a kitchen room and the wall on the road side are very necessary.

The whole of the Estimate has to be sanctioned from the State Grant of the Current Official Year 1908-9 as no amount is reported to be available at the credit of the temple.

Further Items 2 + 3 are the only items that appear to be necessary, but in view of the fact that the temple has no funds + that just spent about 700 Rs on repairs only a couple of years ago it seems doubtful whether another

Muzrai Secretariat

File No. / / of 190 6

from State funds should be made

row - 71
2nd (✓) 4708.

CSB
20/7/08

I concur. Other temples
should have their turn.
Please keep this for disposal
along with similar appli-
cations for allotments
from the State grant.

WVH

23/7/08

Put up a list of such
applications already
granted & still pending

CSB
14/11/08

Secretary -

I shall visit the temple and submit
my proposals.

Ors order.

Approved

V. S

Keep for Personal inspection

22/7/08

22/7/08

Page ()

File No.

of 190

Muzrai Secretariat

Muz File No. 42 of 1906

Serial
No.Kibigini Muzgratbha
Under Secretary

40589

I inspected this paper this morning. The next important item of work is the report of the Northern Circuit work. The meaning has been explained in the Assistant Engineer's report. The other works being not meant, Rs 8000 is sanctioned for the current year. The report is in charge of the District Engineer being also reviewed. Draft submitted to the Council.

Ship A.

157)

A. M. Muzgratbha

1st July 1906

Issue after approval by the Dewan.

18/6/06

H. M. Muzgratbha

18/6.

11/6

Submitted to Dewan

A. M. Muzgratbha

19/6/06

1247
29/6/06

Issue

23/6/06

30/6/06

To, Comptroller, Chief Engineer, S. C. Bangalore
and Mysore Engineer No 2380 3 27 23 6-09
Sanctions the Estimate for Rs. 8000/-

Serial
No.

for repairing the northern wall of the
Temple and directs that the Charges for
Establishment and other purposes need
not be separately levied and that the
work should be carried out by the
P. W. Departt at an early date

From the Executive Engineer, Bangalore Division;
No 897 D, 12th September 1909.

States that the above sanctioned
Estimate has to be modified for reasons
explained in the ~~enclosed~~ report
accompanying the revised Estimate
for Rs 1050/- which is submitted for
sanction.

A sum of Rs 170/- exceeds the sanctioned Estimate.

Under Secretary's order

"Continue note early and put up draft sanc-
tion as, excess from the Current year State Grant"
Draft Sub 2 for explanation, then come in. The
reason for modifying the estimate as stated
in 20/9/09 with ref to 15/9/09. - Atkinson

12/9/09

Draft appd by 20/9

20/9/09

20/9/09

Atkinson
20/9/09

G.O no 879-82 of 24.9.10 To Engrs, Bangalore
Compt. & Engrs Bangalore from the revised

etariat. nue

File No.

of 190

Serial
No.

estimate for Rs 1050, the excess charge being met
from State Grant.

SL1

190 6.7

From

The Dy. Commissioner
Bangalore Dist.

To

The Secy. to the Govt. of Mysore
Mysore Deple.

Dated 12.

Despatched 15 April 1907.

Received

General No.

U.S. No. 143

Enclosure No. 1/200

Solicit to sanction for
the repair of Sri Venk-
kopalaswami temple
at Chickmolur in the
Channarayana Taluk.

MYSCORE C

4674

A.N. 4

15/4/07

16/4/07

Dep
Bangalore Dis
M-P. 143
E. Sec. Bangalore 12th April 1907

To Mr. H. H. Sparkes Esquire
Deputy Commissioner
Bangalore District

From Mr. Ananthaswami Rao Esquire B. A. B.
Secretary to the Government of
Mysore
Mysore Department.

Sir,
I have the honor to forward
herewith correspondence ending
with Channarayana Sub Division Officer's order
no 1549 of 24th March 1907, re the repairing
of Sri Venkateswara Temple at Channarayana
-moola in the Channarayana Taluk. I have
the honor to request that you will be so
good as to obtain Government sanction
for the execution of the work as per estimate
herein enclosed. The cost of the estimate viz
Rs 580/- will have to be met out of the
State Funds as it is reported that there
are no

at the credit of the temple

The temple being situated on the side of the Bangalore Mysore road and being considered an ancient and important temple, it is very necessary that the same should be kept in good order.

I have the honor to be,
Sir

Your most Obedient Servant,

H. P. S. S.
Deputy Commissioner
my

consulted and the Estimate herewith returned may be checked, in
revised by him. The Chief Engineer will be requested to grant
his permission in this behalf.

Cost of a bed room or kitchen is really
new, and the estimate therefor may be separately submitted.

I have the honor to be,

Sir,

Your most obedient servant,

stt)

[Signature] 24/4/09
Secretary.

5090

(One of the above is forwarded to the Chief Engineer
for his consideration, and the local P.W. Officer at Chen-
nai may be kindly instructed to proceed on the work above
referred to.

Information is also requested as to whether the repairs
to the building on the P.W. (No. 1101-3, dated
1908) have been completed by the P.W. Department.

Yours Order,

stt)

[Signature]
Secretary.

3/10

Muz. 1 A]

190

From

SL 4

To

The Deputy Commr.

Bangalore Dist.

Dated

Despatched

14 10.07

Received

General No. 1912
No.

Enclosure No. 1/1

In continuation of
this office letter no 5089
dated 29th April 1904, has -
the honor To forward here-
with petition registered no. 1431
dated 26th September 1904
from Alasingla bhar and
certain others of Malur
in the Chennapatna Taluk
pointing out the necessity
of certain repairs to the
Sri Gopalakrishnaswami

emple at Chichka Mahua
and also for an ^{enhanced} cash grant
for the conduct of Suje
and other services in the
temple, and to request that the report
already called for may be submitted at an
early date. By order

no
1969
D.D. 9/10/69
4/11/69
Secretary.
Encl. to the P. & A. 4/11/69

SL 5

Mysore public works department,
Office of the Superintending Engineer,
Eastern Circle.

No. 1486

Dated Bangalore 26 th. March 1908.

From,

Y. Srinivasa Rao, Esquire B.A.,
Superintending Engineer,
Eastern Circle.

To,

L. Anantavani Row Esquire B.A.,
Secretary to the Government of M.
of the Mahajan of Mysore.

Rural department.

Sir,

With reference to your No. 3090 dated 25-4-07 to the
Chief Engineer regarding certain works required to the
Sri Gopalakrishnaswamy Temple at Chickmallur in the Chennarayana
Taluk, I have the honor to forward for your information
a copy of the Bangalore Division Executive Engineer's No.
1413/213 dated 21st. 3.08.08, reporting that he has sent to
the Deputy Commissioner a fresh estimate amounting to Rs.
1930/- for the works required and that the repairs previously
sanctioned to the same temple have already been completed.


I have the honor to be,

Sir,

Your obedient servant.

Y. Srinivasa Rao

Superintending Engineer,
Eastern Circle.



Mysore publ

From,

The Superintending Engineer
Eastern Circle.

To,

The Secretary to the Government
of M.P.; the Maharajah of Mysore
Muzrai Department.

No. 1486

Dated $\frac{28}{20}$ 3-08

Enclosures.

Sri Gopalakrishnaswamy Temple at

Chickballur in the Chennarayana Taluk

Represented
Chakkar
30/3/08
h
L
DfL Sub?
4/4/08

1453

The Executive Director
Bangalore Division.

The Superficialis is a deep
Fascial Capule.

Dated 21 st. March 1908.

Despatched

Received

General No. 1416/10.
No.

Enclosure No.

גויסטרנדיר, פון א צער'ס זיט.

2728 dated 1-5-07 for ardrin co.

SI TEXAS PERDÉ SU LIBERTAD

20-4-07, ^{requesting} ~~re-appointing~~ ~~to~~ ~~the~~ ~~same~~ ~~post~~

• every letter sent to the President

Planner will call Division of...

The H₂ fluxes for several stars are com-

found all of gri were up last night

while at place, hear in the same way.

Now a Talk, Devoted to the Fair

I SPECIFY LOCATION 26.

— — — — — 0 — — — — —

II. 2. 6. 1. 2. 3. 4. 5. 6. 7. 8. 9. 10. 11. 12. 13. 14. 15. 16. 17. 18. 19. 20. 21. 22. 23. 24. 25. 26. 27. 28. 29. 30. 31. 32. 33. 34. 35. 36. 37. 38. 39. 40. 41. 42. 43. 44. 45. 46. 47. 48. 49. 50. 51. 52. 53. 54. 55. 56. 57. 58. 59. 60. 61. 62. 63. 64. 65. 66. 67. 68. 69. 70. 71. 72. 73. 74. 75. 76. 77. 78. 79. 80. 81. 82. 83. 84. 85. 86. 87. 88. 89. 90. 91. 92. 93. 94. 95. 96. 97. 98. 99. 100. 101. 102. 103. 104. 105. 106. 107. 108. 109. 110. 111. 112. 113. 114. 115. 116. 117. 118. 119. 120. 121. 122. 123. 124. 125. 126. 127. 128. 129. 130. 131. 132. 133. 134. 135. 136. 137. 138. 139. 140. 141. 142. 143. 144. 145. 146. 147. 148. 149. 150. 151. 152. 153. 154. 155. 156. 157. 158. 159. 160. 161. 162. 163. 164. 165. 166. 167. 168. 169. 170. 171. 172. 173. 174. 175. 176. 177. 178. 179. 180. 181. 182. 183. 184. 185. 186. 187. 188. 189. 190. 191. 192. 193. 194. 195. 196. 197. 198. 199. 200. 201. 202. 203. 204. 205. 206. 207. 208. 209. 210. 211. 212. 213. 214. 215. 216. 217. 218. 219. 220. 221. 222. 223. 224. 225. 226. 227. 228. 229. 230. 231. 232. 233. 234. 235. 236. 237. 238. 239. 240. 241. 242. 243. 244. 245. 246. 247. 248. 249. 250. 251. 252. 253. 254. 255. 256. 257. 258. 259. 260. 261. 262. 263. 264. 265. 266. 267. 268. 269. 270. 271. 272. 273. 274. 275. 276. 277. 278. 279. 280. 281. 282. 283. 284. 285. 286. 287. 288. 289. 290. 291. 292. 293. 294. 295. 296. 297. 298. 299. 300. 301. 302. 303. 304. 305. 306. 307. 308. 309. 310. 311. 312. 313. 314. 315. 316. 317. 318. 319. 320. 321. 322. 323. 324. 325. 326. 327. 328. 329. 330. 331. 332. 333. 334. 335. 336. 337. 338. 339. 340. 341. 342. 343. 344. 345. 346. 347. 348. 349. 350. 351. 352. 353. 354. 355. 356. 357. 358. 359. 360. 361. 362. 363. 364. 365. 366. 367. 368. 369. 370. 371. 372. 373. 374. 375. 376. 377. 378. 379. 380. 381. 382. 383. 384. 385. 386. 387. 388. 389. 390. 391. 392. 393. 394. 395. 396. 397. 398. 399. 400. 401. 402. 403. 404. 405. 406. 407. 408. 409. 410. 411. 412. 413. 414. 415. 416. 417. 418. 419. 420. 421. 422. 423. 424. 425. 426. 427. 428. 429. 430. 431. 432. 433. 434. 435. 436. 437. 438. 439. 440. 441. 442. 443. 444. 445. 446. 447. 448. 449. 450. 451. 452. 453. 454. 455. 456. 457. 458. 459. 460. 461. 462. 463. 464. 465. 466. 467. 468. 469. 470. 471. 472. 473. 474. 475. 476. 477. 478. 479. 480. 481. 482. 483. 484. 485. 486. 487. 488. 489. 490. 491. 492. 493. 494. 495. 496. 497. 498. 499. 500. 501. 502. 503. 504. 505. 506. 507. 508. 509. 510. 511. 512. 513. 514. 515. 516. 517. 518. 519. 520. 521. 522. 523. 524. 525. 526. 527. 528. 529. 530. 531. 532. 533. 534. 535. 536. 537. 538. 539. 540. 541. 542. 543. 544. 545. 546. 547. 548. 549. 550. 551. 552. 553. 554. 555. 556. 557. 558. 559. 560. 561. 562. 563. 564. 565. 566. 567. 568. 569. 570. 571. 572. 573. 574. 575. 576. 577. 578. 579. 580. 581. 582. 583. 584. 585. 586. 587. 588. 589. 590. 591. 592. 593. 594. 595. 596. 597. 598. 599. 600. 601. 602. 603. 604. 605. 606. 607. 608. 609. 610. 611. 612. 613. 614. 615. 616. 617. 618. 619. 620. 621. 622. 623. 624. 625. 626. 627. 628. 629. 630. 631. 632. 633. 634. 635. 636. 637. 638. 639. 640. 641. 642. 643. 644. 645. 646. 647. 648. 649. 650. 651. 652. 653. 654. 655. 656. 657. 658. 659. 660. 661. 662. 663. 664. 665. 666. 667. 668. 669. 670. 671. 672. 673. 674. 675. 676. 677. 678. 679. 680. 681. 682. 683. 684. 685. 686. 687. 688. 689. 690. 691. 692. 693. 694. 695. 696. 697. 698. 699. 700. 701. 702. 703. 704. 705. 706. 707. 708. 709. 710. 711. 712. 713. 714. 715. 716. 717. 718. 719. 720. 721. 722. 723. 724. 725. 726. 727. 728. 729. 730. 731. 732. 733. 734. 735. 736. 737. 738. 739. 740. 741. 742. 743. 744. 745. 746. 747. 748. 749. 750. 751. 752. 753. 754. 755. 756. 757. 758. 759. 760. 761. 762. 763. 764. 765. 766. 767. 768. 769. 770. 771. 772. 773. 774. 775. 776. 777. 778. 779. 780. 781. 782. 783. 784. 785. 786. 787. 788. 789. 790. 791. 792. 793. 794. 795. 796. 797. 798. 799. 800. 801. 802. 803. 804. 805. 806. 807. 808. 809. 810. 811. 812. 813. 814. 815. 816. 817. 818. 819. 820. 821. 822. 823. 824. 825. 826. 827. 828. 829. 830. 831. 832. 833. 834. 835. 836. 837. 838. 839

THEY ARE THE ONLY TWO WHO HAVE BEEN

Wash DC 20540

[illegible]

Commissioner for disposal with this Office

21-3-08 and it provides for constructing the compound
construction - a small kitchen as also petty repairs require
for the Anjanaya Swamy's temple close by.

11. The estimate for Rs. 672/- sanctioned in government
order no. ⁹⁴⁴ 2552 dated 18-11-05 for repairs to this
temple has already been completed.

(30) R. G. Venkatachari
to: Mr. Mr. Tanalore Division.

" C O P Y ".

Perumal

Superintending Engineer,
R. Tanalore Circle.

Muz. 1]

190

From

SL 6

To

The Deputy Commissioner
Bangalore District

Dated

Despatched 15-4-1908

Received

General No. 4491.
No.

Enclosure No. 1.

In continuation of this
Office docket no 1918 D 14th
October 1907, has the honor
to forward herewith a
Copy of Chief Engineer's to
Suptg Engineer's letter no 1486
D 28th March 1908 stating
that an estimate for repairing
the Sri Gopalakrishna Swami
temple at Chikkamallur
in the Channarayana Taluk

has been forwarded to the
Dy Commr of the Bangalore D^h,
and to request that the
Estimate called for may
be submitted at an
early date.

R.O.
11/15/44/68
Secretary.
H. S. 1008.

SL7
1907.8.

From

The Dy. Commissioner
Bangalore Dist.

To

The Secy to the Govt of Mysore
Mysore Deft.

Dated 1st

Despatched 2nd May 1908.

Received

General No.

M. S. No. 124

Enclosure No.

4 etc.
1 tracing
1 plan
1 est.
1 sketch

His N- 491 of 15-4-08

Submits plan and estimate
for repairing the Sri
Gopalakrishna Swami Temple
at Chickmalar in the
Channarayana Taluk.

4424
4/5/08

Refers

and
25/08
by

Note cont? sent?

T.S.-08

Office of the Dy. Commissioner,

M.S.No. 124..

Dated Bangalore, 1st May 1908.

From

8.5

B. J. Kumarasamy Naik Esquire B.A.,

Deputy Commissioner, Bangalore District.

To

L. Anantasamy Rao Esquire B.A.,

Secy. to the Govt. of H.H. the Maharaja of Mysore,

Muzrai Department.

Sir,

With reference to correspondence ending with your docket No. 4491 dated the 15th April 1908, in re the repairing of Sri Gopala Krishnaswami Temple at Chickmalur in the Chennapatna Taluk, I have the honor to forward herewith plan and estimate --- received from the Executive Engineer with his docket No. 1420/462 dated the 20th March 1908.


2. As it was stated in your letter No. 5089 dated the 29th *April* 1907 that the repairing of the compound wall had to be given up on a previous occasion for want of funds at the credit of the --- temple, the estimate was forwarded to the Closepet Sub-Division Officer to report the items of works which are to be taken up -- urgently. The Sub-Division Officer after personal inspection states in his Yadi No. 1534 dated the 21st April 1908, that the construction of the kitchen room and the wall on the road side are very necessary.

3. The vernacular papers bearing on the subject are also herewith forwarded for reference and kind return.

I have the honor to be,

Sir,


Your most obedient servant,



Deputy Commissioner,

Bangalore District.

B.N.S.



06

12/5

Muz. 1]

190

sl8

From

To The Deputy Commr.

Bangalore Dist.

Dated

Despatched 14.5.08.

Received

General No. 5008
No.

Enclosure No.

This no 124 of 14 May 1908
submitting for sanction
an estimate for repairing
the Sri Gopala Krishna
Swami temple at Chik-
maller, Channarayana Taluk

With reference to the
above, has the honor to
request that a Treasury
Certificate for the

M.S. amount available at
From the cre dit of the temple

To May be Submitted at
an early date. The encls. are returned in
Sir Office.

BO

13/5/08

11/5/08

Secretary

W

14/5/08


doc
Sri
Tal
rec
dat

2.
190
on
ter
Off
ur
in
-t:
ne

3.
he

B.

F42 06 \$19
— 1907.8.



From

The Dy. Commissioner
Bangalore Dist.

To

The Secy. to the Govt. of Mysore
Mysore Dist.

Dated 20.

Despatched 25 June 1908

Received

General No.

H.S. No. 151

Enclosure No. one.

Ref 1.7

And

47608

by
✓

note Cont? 18.6.08

2/7/08

This N- 5008 of 4.5.08.

Reports there is no
amount at the credit of
Sri Gopala Krishnaswami
temple at Chicka Malur,
Channarayana Taluk.

Office of the Deputy Commissioner Pan al

M.S.No.157.

Dated Bangalore, 20th June 1908.

E - /

From

B. J. Kumaraswamy Naik Esquire B.A.,

Deputy Commissioner, Bangalore District.

To

L. Anantaswamy Rao Esquire B.A.,

Secy.to the Govt.of H.H.the Maharaja of Mysore,

Muzrai Department.


Sir,

With reference to your docket No.5008 dated the 14th May 1908, I have the honor to state that the Amildar of the --- Chennapatna Taluk in his No.462 dated the 27th May 1908 (herewith sent) reports that there is no amount at the credit of the Sri Gopalakrishnaswamy Temple at Mallur.

I have the honor to be,

Sir,

Your most obedient servant,



Deputy Commissioner,

P.H.S.

Bangalore District.



Mr 563

$$\begin{array}{r} 9674 \\ - 7206 \\ \hline 2468 \end{array}$$

7-20 656

~~అం-~~ నా సహుల క్రిష్టియన్ బ్రదర్స్ కు సంతకము
 నా నానా

25. విజయ చక్రము ప్రాప్తమైనది గాన.

తెలుగు భాషలోని పుస్తకాల (క) నాంబరం ౧౭

7. m. s. 352
 07.08.

1. ಪ್ರಾಚೀನ ಕಾವ್ಯ ಕೃತಿಗಳನ್ನು ಈ ಕೆಳಕಂಡಂತೆ
 2. ಪ್ರಾಚೀನ ಕಾವ್ಯ ಕೃತಿಗಳನ್ನು ಈ ಕೆಳಕಂಡಂತೆ
 3. ಪ್ರಾಚೀನ ಕಾವ್ಯ ಕೃತಿಗಳನ್ನು ಈ ಕೆಳಕಂಡಂತೆ
 4. ಪ್ರಾಚೀನ ಕಾವ್ಯ ಕೃತಿಗಳನ್ನು ಈ ಕೆಳಕಂಡಂತೆ
 5. ಪ್ರಾಚೀನ ಕಾವ್ಯ ಕೃತಿಗಳನ್ನು ಈ ಕೆಳಕಂಡಂತೆ

87 20-5-18

Pringel's hat

నానా
 పరిశ్రమలకి పోయి
 2009
 21.5.08

Please send it early

10y. Connors.
24. Transverse Ditch

$$\begin{array}{r} 10.462 \\ \hline 92 \end{array}$$

Signature of _____

Fragebogen

உலகநாடுகள் உலகநாடுகள்

nmw/

இந்தக் குறியைக் கொண்டு வருவது.

30578
25-5-08

Neubergenthal

for Exercise

Murrai 840

Read -

Correspondence ending -
with letter No 151 dated
25th January 1908, from
the Deputy Commissioner
Bangalore District, sub-
mitting an estimate
amounting to Rs 1930/-
for further repairs to
the Sri Gopalakrishna
Swami temple at Chikka
Shalva in the Channa-
patna Taluk.

Note dated the 9th June
1909, by the Murrai Super-
intendent and Under
Secretary to the Govern-
ment of Mysore.

No. 2320-3-2/23.6.22, Order thereon No.
Muzt 42 H.C.

Recd. 21/2/23
Re. 21/2/23
1/2/23
1/2/23
1/2/23

The Deputy Commissioner
has submitted for sanction
an estimate for Rs 1930/-
for the works specified

below :-

- | | |
|---|-------|
| (1) Construction of a Kitchen | 390/- |
| (2) Re-construction of Northern.
- compound wall | 880/- |
| (3) Repairs to main temple | 120/- |
| (4) Repairs to the Sri }
Aiyanezabwani temple } | 274/- |
| (5) Estt., tools & Plant charges | 266/- |

The Murray Superintendent after personally inspecting the temple recommends that the re-construction of the Northern compound wall which is urgently called for may be sanctioned from the State funds as the temple has no savings at its credit and adds that in view of the fact that the charge is entirely paid from the State grant the charges on account of Establishment ^{to} other ~~charges~~ may be remitted.

Accepting the Murray Superintendent's recommendation, Government

the estimate for Rs 880/- only for repairing the northern wall and to direct that the charges for establishment and other purposes need not be separately levied.

The work should be carried out by the P.W. Department at an early date.

The Comptroller is requested to transfer to that Department, the sanctioned amount from the State grant of the current year

*it is
20/11/1919*

H. J.

dft

10/11/1919
Secretary

To,

- The Comptroller, Mysore
- Chief Eng^r of Mysore,
- Dy Comm^r, Bangalore
- Muzrai Superintendent
in Mysore

From the *Engineering*
Bangalore *42-06*
Division

Dated 12 Sept 09 (Muzaroy Branch)
13

Received

General No. 897
No

Enclosure No. $4 + 2 = 6$

Sir,

I have the honor to state that the Estimate of Rs 880/- for repairing the Northern Compound wall of the Bhikainalur Sri Venkateswamy Temple, sanctioned for Rs 880/- in Government Proceedings No 2380-3 may 42-06-10 of June 1909, had to be modified for reasons explained in the report. A modified amounting to Rs 1050/- has been prepared and is herewith submitted.

herewith

early transmission to the

Eastern Circle. -

I have the honor to

Sir

Your most obedient

H. H. M. Aiyar
Executive Officer

Bangalore Division

Enclosures

1 Oyl. Estimate

1 Modified Estimate

1 Report

1 Sketch

4

1 Quartered plan

1 - do - do drawing

6

Mysore P. W. Department,

Bangalore Division.

Estimate No. of 1909-'10.

Report to accompany the Modified estimate for reconstruction of the dilapidated northern compound wall of Sri Venugopalaswami's temple at Mallur, Chennarayana Taluk.

Reference Chennarayana P. W. Sub Divisional Officer's estimates

2. 1. 1910

An estimate amounting to Rs 880/- has been sanctioned for this work in Government Proceedings No. 2380-3 Aug 42-06-10 of June 1909. The estimate is for the complete dismantling of the height of the old wall from the top of its foundation to the construction of a new stone in chunam wall 7 feet high in its place. It is proposed to utilise a portion of the cut stone face slabs at the bottom of old wall for uping the new wall.

properly. A new

- pared. From this it

that the bottom portion of
for $4\frac{1}{2}$ feet height consists
thick heavy slabs vertically

at both faces of the wall,
space between them being

in with brick bats, rubbish
earth. To bind these slabs -

throughout, bond stones are
inserted 15' to 20' apart. Over

this a brick faced wall

similar hearting is run up
with coping and plastering over

4. This structure has gone one
foot out of plumb, the foundation
on the alluvial soil having been
saturated by the court-yard
water, & one taking care to
drain the yard properly.

5 The brick work must therefore
go, but the complete removal
of the fine dressed slabs would

would be a pity. The outside slabs have a nice inward batter like a French fortress and all that is needed for these is fine pointing. The inside slabs which are 1 to $1\frac{1}{2}$ " out of plumb require removal and re-pointing to 1:1.

The earth between may be removed and the space filled with rough jelly concrete. Over the bottom thus rectified now stone in chunam wall 3 feet bottom 2 feet top may be raised with brick in chunam coping.

b. This is the way in which the western wall has been dealt with by old Engineers who built the Lion's bridge and the front wall is also similarly dealt with, only the walling above, slabs is of brick in chunam instead of stone in lime, adopted for the main wall as it is the one exposed to water action during high flood.

For uniformity of appearance,
the wall may be plastered inside
of being pointed.

7. The Modified estimate to
Rs 1059/- against Rs 880/- of sanctioned
estimate. Early approval is
sanctioned estimate. Early approval
is solicited to go on with the work
as per modified proposals.

Sd/- K. Krishna Kumar

10-4-09

Executive Engineer

File No. 42-06

Serial No.

Diary No. of letter replied to _____

Proceedings of the Government of His Highness
the Maharaja of Mysore.

GENERAL AND REVENUE
SECRETARIAT.

()

READ.—

Govt No. N^o 2380-3 dt 23rd June 1909
N^o 42 06-10

, the

190

Date of issue

24th Sept 1909

Signed by

M^{rs} A. S. Dyen

Sanctioning an Estimate for Rs 880/- for repair-
ing the northern Compound wall of the
Sri Kumbhagata Krishna Swami Temple at
Chickamallur, Channarayana Taluk
to No. 897 dt 12th September 1909 from

~~ORDER THEREON.~~ No.

the Ex Engineer, Bangalore dt 2nd September 1909,
for sanction a revised Estimate for
Rs 1050/- for the above work.

Order Thereon N^o 849-82 dt 14.

The Executive Engineer states

that estimate at Rs 1000/- is

over

SUBJECT

necessary to the Strong Compound
wall have been omitted in the
Sanctioned Estimate and Submit
for sanction a revised Estimate
for Rs 1050/- providing therein for
bond stone &c

Under the ~~above~~ Circular
No. 1274 dated 12/11/1907
the revised Estimate for Rs 1050/-
is sanctioned. The excess charge

Rs 170/- being met from the State
Grant of the Current Financial Year

2 The work should be carried
out to the P.W. Department & completed.

3 The Comptroller is requested
to place the excess ^{amount} sanctioned
~~Rs 170/-~~ ^{Via} Rs 170/- at the disposal
of the P.W. Department

4 The ^{original} Estimate sanctioned in the
No. 1274 above is hereby cancelled

Copy kept with of
Report in our file
22/9/1907

22/9/1907

for Secretary

W. S. S. S.

23/9/07

- To The Chief Engineer of Mysore with the sanctioned Estimate & other enclosures
- " Comptroller, Mysore Govt
 - " M. Comm., Bangalore Dt.
 - " Executive Engineer, Bangalore Dist.
 - " Municipal Engineer, Mysore